



Coated coil installed in April of 2009. Picture taken July 11, 2009.

Picture is from 1,400 sf townhouse with tainted Chinese drywall throughout the walls and a mix of 5/8" non-tainted and 1/2" tainted drywall on the ceilings.