



Date: 7-3-09  
Initial picture of copper pipe sections placed on top of filter inside air handler under coil.  
Top sample is with teflon coating.  
Bottom sample is without teflon coating.

Field study to determine effectiveness of teflon coating as a means to protect or extend the life of evaporator coils in a home containing tainted Chinese drywall.



Date: 7-19-09  
Copper pipe sections after 16 days of exposure.  
Top sample is with teflon coating,  
bottom sample is without teflon coating.